BRAUN

Machine wash, cold (up to 30-40°C)

Machine wash, warm (up to 60°C)

Machine wash, hot (up to 90°C)

Hand wash

Do not wash, dry cleaning

No bleach

Tumble dryer

Tumble dryer cold

Tumble dryer warm

Tumble dryer hot

Dry cleaning only

No dry cleaning

No hot ironing, 110°C max

Moderately hot ironing, 150°C max

Hot ironing, 200°C max